



<b>Department/Activities/Working Area</b> BaySystems SouthChina	
<b>Material Name</b> AK-8805	Standard <b>Version</b> 01
<b>1. Hazardous substances designation</b> Color: transparent, yellowish, Form: liquid, Odor: slight, State of matter: Liquid	
<b>2. Dangerous to humans and environment</b> R10: Flammable R20/21/22: Harmful by inhalation, in contact with skin and if swallowed. R34: Causes burns R52/53: Harmful to aquatic organisms, may cause long-term adverse effects in the aquatic environment. WGK: Highly water endangering	
<b>3. Preventive measures and behavior rules</b> Avoid contact with eyes and skin. Eye protection: safety glasses Hand protection: gloves with coating, breakthrough time not tested, immediately dispose after contamination. Breathing protection: Half mask with filter Take arrangements against electrostatic charge.	
<b>4. Behavior in the case of danger</b> Avoid contact with eyes and skin. Eye protection: safety glasses Hand protection: gloves with coating, breakthrough time not tested, immediately dispose after contamination. Breathing protection: Half mask with filter Extinguishing agent: CO <sub>2</sub> , extinguishing foam, in case of greater fires also water spray. Scatter leaked product with binder, adsorb mechanically and fill in to labelled lockable canister. Do not allow that leaked product enters canalization and/or soil.	
<b>5. First Aid - emergency call 32812104</b> Eye contact: The eyes with opened eyelids thoroughly with eye rinsing liquid or with water rinse. (Eye) physician should be visit. Skin contact: Take off clothes immediately which are contaminated with product. Contaminated skin have to be cleaned thorough with a lot of water and soap. Skin thoroughly with much water and soap wash. Swallow: Water to drink leave. Mouth repeated rinse out. No vomiting cause. Subsequently, consult physician.	
<b>6. Proper disposal</b> Waste: Can be burned considering the legal editions in a combustion plant.	

